


Key:

PPE Probable Point of Entry

 Waste Rock Pile



ecology and environment, inc.
International Specialists in the Environment
Seattle, Washington

UPPER COLUMBIA RIVER
MINES AND MILLS
PRELIMINARY ASSESSMENTS
AND SITE INSPECTIONS
Stevens County, Washington

Figure 6-29
SIERRA ZINC MINE/MILL
SITE MAP

Date:
8-20-02

Drawn by:
AES

10:START-2\01020028\fig 6-29